























	9	10	11	12	13
H min	1710mm	1900mm	2090mm	2280mm	2470mm
H max	2115mm	2350mm	2585mm	2820mm	3055mm




h	ST01a	ST01b
190 mm	0x	0x
195 mm	1x	0x
200 mm	2x	0x
205 mm	3x	0x
210 mm	4x	0x
215 mm	0x	1x
220 mm	1x	1x
225 mm	2x	1x
230 mm	3x	1x
235 mm	4x	1x





max. 200 kg

 12x	 1x	 13x $\varnothing$ 108x200 mm	 26x $\varnothing$ 115 x 3 mm	 1x	 1x $\varnothing$ 60 x 1000x4 mm
 1x $\varnothing$ 100 x 3 mm	 2x	 1x $\varnothing$ 60 mm	 25x	 12x	 1x
 1x $\varnothing$ 40x2x180 mm	 1x	 1x $\varnothing$ 40x3x6000mm	 5x $\varnothing$ 6x1x6000mm	 13x $\varnothing$ 22x2x1275 mm	
 1x $\varnothing$ 22x2x1030 mm	 4x M20 x 1000 mm	 13x M20 DIN-EN 24035	 4x M20 DIN 6334	 4x M8x50 mm	 100x $\varnothing$ 5 x 30 mm
 30x $\varnothing$ 4,2 x 19 mm	 8x $\varnothing$ 6x30mm	 12x $\varnothing$ 6x50mm	 32x $\varnothing$ 4x25mm	 3x M8x25mm	
 2x M6	 2x M6	 10x $\varnothing$ 6 x 12 mm	 12x $\varnothing$ 22 mm	 3x $\varnothing$ 40 mm	 4x $\varnothing$ 12 mm
 14x $\varnothing$ 8 mm					




$x_{\min} = 465 \text{ mm}$



$x_{\max} = 735 \text{ mm}$







$$b = 230 \text{ mm} - a \times 0.33$$






3









4












h	ST01a	ST01b
190 mm	0x	0x
195 mm	1x	0x
200 mm	2x	0x
205 mm	3x	0x
210 mm	4x	0x
215 mm	0x	1x
220 mm	1x	1x
225 mm	2x	1x
230 mm	3x	1x
235 mm	4x	1x



5





6

